


FIG. 3



FIG. 4






FIG. 6

FIG. 7

700

☐ Configuration

File Edit View Tools Window Help

Network Check

Recipient:

712 ☒ E-mail System Address

714 ☐ E-mail Server Address

716 ☐ Router Used by E-mail Server

Sender:

722 ☒ E-mail System Address

724 ☐ E-mail Server Address

726 ☐ Router Used by E-mail Server

Failure Analysis of Systems Network

732 ☒ Ping

734 ☐ SNMP Queries

FIG. 8

800

☐ Administration Output

File Edit View Tools Window Help

812 Last Query of E-mail Addresses: Time Date

814 Last Valid E-mail Address: Time Date

IP Address Status

822 Last Query of IP Addresses: Time Date

824 Sender Mail Server: Down

826 Recipient Mail Client: OK

828 Recipient Mail Server: OK

FIG. 9A




FIG. 9B




FIG. 9C





FIG. 10